

## SERVICE LETTER NO. SL GROB-019

### I. TECHNICAL DETAILS

**1.1 Airplanes affected:**

ALL with Grob-Micro-Benz Clock P/N 115EG-7780 installed

**1.2 Subject:**

ATA-Code: 31-20 Independent Instruments  
Discontinuation of Grob-Micro-Benz Clock Part Number 115EG-7780

**1.3 Reason:**

Due to upcoming obsolescence and supply chain problems of major parts of the Grob-Micro-Benz Clock Part Number 115EG-7780, Grob informs that the clock will be discontinued by **1<sup>st</sup> of August 2023**. Until this date, the clock can be ordered in small quantities and repairs will still be accepted.

**1.4 Information:**

1.4.1 For installation of an alternative clock (accurate time piece) refer to EASA CS-STAN latest Issue. Standard Change CS-SC401d provides guidance for the installation of basic flight instruments (e.g. accurate time piece).

When additional lighting is not required for the readability, Grob can recommend the non-lighted **Adriatica Bord-Stoppuhr 09CH** as suitable alternative:

- Swiss made
- Very good readability
- Stainless Steel housing with mineral glass
- Quartz-controlled Ronda clock unit
- Rotatable outer ring
- Stop function up to 10 hours
- Non-lighted



### II. REMARKS

If you have sold your aircraft in the meantime, would you kindly pass this information on to the new owner and forward his address and aircraft S/N to us. For questions and assistance please contact:

Product Support,  
phone: +49 8268 998105  
fax: +49 8268 998200  
e-mail: [productsupport@grob-aircraft.com](mailto:productsupport@grob-aircraft.com)