



**SERVICE LETTER
NO. SL115-49
NO. SL1121-011**

I. TECHNICAL DETAILS

1.1 Category:

Optional

1.2 Airplanes affected:

G 115E, all S/N
G 115EG, all S/N
G 115TA, all S/N
G 120A, all S/N
G 120A-I, all S/N

1.3 Time of Compliance:

during repair/ replacement

1.4 Subject:

ATA-Code: **52-10, Canopy Lock**

1.5 Reason:

For manufacturing and maintenance reason the design of the canopy lock P/N 115TA-2630 was improved.

1.6 Concurrent documents:

Drawing No. 115TA-2630/1

**G 115 series
G 120 series**



1.7 Accomplishment/ Instructions

- Replace canopy lock P/N 115TA-2630 against canopy lock P/N 115TA-2630/1 IAW Maintenance Manual Chapter 52-10 (or Job Guide 1TG115EG-3-52JG-00-1 for G 115EG)

CAUTION: It is not possible to modify the old standard to the new standard. The locks can be replaced only **completely** one by one !

1.8 Repetitive Actions

N/A

1.9 Mass (Weight) and CG:

N/A

II. PLANNING INFORMATION

2.1 Material & Availability:

P/N new	P/N old	Name	Qty.
115TA-2630/1	115TA-2630	Canopy Lock	1

2.2 Special Tools:

N/A

2.3 Labour costs:

Replacement: 1 hours

2.4 Reference documents:

Illustrated Parts Catalogue G 115E, G 115EG, G 115TA, G 120A, G 120A-I Chapter 52-10

G 115 series
G 120 series



2.5 Credit:

N/A

III. REMARKS

- 3.1 The replacement may be performed by an authorised aviation workshop.
- 3.2 If you have sold your aircraft in the meantime, would you kindly pass this information on to the new owner and forward his address and aircraft S/N to us.
- 3.3 For questions and assistance please contact:

Rudi Vodermeier , Head of Product Support,
phone: +49 8268 998139
fax: +49 8268 998200
e-mail: productsupport@grob-aerospace.de