

Subject: New Issue of the Operations Manual GROB 2500

Concerned: Aircraft Engine GROB 2500 E1/D1, all S/N's

Urgency: not later than 31 December 1994

Procedure: A new issue of the Operations Manual is required for incorporation of Service Bulletins and other modifications and corrections into the Operations Manual GROB 2500.

Actions: In the Operations Manual GROB 2500 all pages of Issue 1 have to be exchanged against the new pages, Issue 2, dated 01.07.94, according to page 1.4 "List of effective pages".


Material: The new pages, Issue 2, dated 01.07.94, can be ordered from GROB with the attached Purchase Order.

Weight and Balance: not affected

Remarks:

1. The exchange of the pages may be performed by a competent person.
2. If you have sold your motorglider in the meantime, would you kindly pass this information on to the new owner and forward his name and address and aircraft S/N to us.

Mattsies, 01 July 1994



Dipl.Ing. J. Altmann
(Airworthiness engineer
certification staff)

LBA approved:

This Service Bulletin is originally written in German and approved by the German LBA on the 5 September 1994 and is signed by Mr. M. Borsum.

The translation has been accomplished to the best of our knowledge and judgement. In case of doubt, the German original is authoritative.