



Subject: Exchange of the engine mount.

Affected: Motorglider GROB G 109, serial numbers 6010 up to 6073 (inclusive).

Accomplishment: Within the next 50 service hours, but not later than July 31, 1982.

Reason: During operation of the engine model LIMBACH L 2000 EB 1.A together with the propeller model HOFFMANN HO - V 62 R / L 160 T it came to longitudinal oscillations on the engine.

Required action:

1. Dismantling of the engine.
2. Exchange of the engine mount.
3. Installation of the engine.

Material: Engine mount according drawing no. 109-6110 with modification from 14. 5. 82.

Weight and Balance: No influence by exchange of the engine mount.

Remarks: Carrying out of the required action only by Limbach Motorenbau Königswinter or Grob. Exep-tions can be made for foreign owners after consultation with Grob.

Matties, May 14, 1982

LBA approved

gez. i.A. Dipl. Ing. H. Wilser

May 28, 1982

Datum	ersetzt Ausgabe vom	Bearbeitung		Seite
-------	---------------------	-------------	--	-------