



Subject: Revision of the Flight Manual GROB G 115/ G 115A

Concerning: G 115/G 115A all S/N's

Urgency: before 31 December 1992

Procedure: A revision of the Flight Manual is required for incorporation of Service Bulletins and corrections into the Flight Manual Issue 2 of the G 115/ G 115A.

Actions: All pages of the Flight Manual Issue 2 according to page 0-3 (Log of Revisions), Revision 1, dated 13.08.92 must be exchanged.

Material: The relevant pages will be submitted as an attachment to this Service Bulletin.

Weight and Balance: not affected

Remarks:

1. The exchange must be carried out by a competent person and has to be certified in the logbook by an authorized inspector.
2. If you have sold your aircraft in the meantime, we would kindly ask you, to pass this information immediately to the new owner and forward his address and aircraft s/n to us.

Mattsies, 13 August 1992

LBA approved

The German original of this Service Bulletin has been approved by the LBA on the ~~31.8~~^{31.8} August 1992. The translation has been accomplished to our best knowledge and judgement. In case of doubt, the German original is authoritative.

Dipl.Ing. J. Altmann
(Airworthiness engineer
Certification staff)