



Doc. No.: 2500.TM.001		Grob Aircraft AG									
Chapter: 2											
Type: G 2500		Service Bulletins							18. April 2017		
LBA-TCDS No.: 4601		(issued / in preparation)									
SB-No.	ÄM No.	Subject	Date of issue	G 2500 E1	G 2500 D1				Major Change	Minor Change	Remarks
TM 4601-1		Service time between two overhauls (TBO) of GROB 2500 E1	24.10.83	x							LBA approved: 04.11.1983
TM 4601-1/2		Service time between two overhauls (TBO) of GROB 2500 E1 (300 hours)	12.06.84	x							LBA approved: 20.06.1984; ersetzt / supersedes TM 4601-1
TM 4601-2		Check and exchange of cylinder and intake pipe of GROB 2500 E1	30.06.84	x							LBA approved: 17.07.1984
TM 4601-1/3		Service time between two overhauls (TBO) of GROB 2500 D1 (300 hours)	18.12.84		x						LBA approved: 16.01.1985 ergänzt / supplements TM 4601-1/2
TM 4601-1/4		Service time between two overhauls (TBO) of GROB 2500 E1 and GROB 2500 D1 (600 hours)	19.09.85	x	x						LBA approved: 20.09.1985 ersetzt / supersedes TM 4601-1/2 und / and TM 4601-1/3
TM 4601-3		Equipment of the G2500 E 1 with a vacuum pump	05.02.86	x							LBA approved: 24.02.1986
TM 4601-1/5		Service time between two overhauls (TBO) of GROB 2500 E1 and GROB 2500 D1 (900 hours)	25.09.86	x	x						LBA approved: 25.09.1986 ersetzt / supersedes TM 4601-1/2; TM 4601-1/3; TM 4601-1/4;
TM 4601-4		Modification of the cylinder head seat	18.01.88	x	x						LBA approved: 03.02.1988
TM 4601-1/6		Service time between two overhauls (TBO)	20.10.88	x	x						LBA approved: 03.02.1988
TM 4601-1/7		Service time between two overhauls (TBO)	18.07.94	x	x						LBA approved: 05.09.1994
TM 4601-5		Inspection and modification of the lower Slick magneto	08.10.92		x						LBA approved: 04.11.1992
TM 4601-6		Exchange of the toothed rings of the magnetos	20.10.92	x	x						LBA approved: 04.11.1992
TM 4601-7		Inspection of the float needle valve in L/H and R/H carburettor	20.09.93	x	x						LBA approved: 05.10.1993
TM 4601-7/2		Installation of alternative float needle valves	01.10.03	x	x						
TM 4601-7/3		Installation of alternative float needle valves	30.05.05	x	x						
TM 4601-8		Inspection of the cylinder head valve seat	18.07.94	x	x						LBA approved: 05.09.1994

G 2500 Engine

SB are listed according to number, not date of issue
 X = applicable N/A = not applicable P = installation during production

Doc. No.: 2500.TM.001		Grob Aircraft AG									
Chapter: 2											
Type: G 2500											
LBA-TCDS No.: 4601		Service Bulletins (issued / in preparation)						18. April 2017			
SB-No.	ÄM No.	Subject	Date of issue	G 2500 E1	G 2500 D1				Major Change	Minor Change	Remarks
TM 4601-9		Optional installation of spark plugs type CHAMPION REN 30S	18.07.94	x	x						LBA approved: 05.09.1994
TM 4601-10		New issue of the Operations Manual GROB 2500	01.07.94	x	x						LBA approved: 05.09.1994
TM 4601-11		Revision of the Operations Manual GROB 2500	05.10.94	x	x						LBA approved: 24.10.1994
OSB 4601-12		Reworking of cylinder heads	07.02.11	x	x					x	
OSB 4601-12/1		Reworking of cylinder heads	17.02.11	x	x					x	
OSB 4601-12/2		Reworking of cylinder heads	07.03.11	x	x					x	

SB are listed according to number, not date of issue
 X = applicable N/A = not applicable P = installation during production