



SERVICE BULLETIN NO. OSB1078-133

I. TECHNICAL DETAILS

1.1 Category:

Optional

1.2 Aircraft affected:

G 115; G115A; G115B; G115C

1.3 Time of Compliance:

at holders discretion

1.4 Subject:

ATA-Code: 25-10 Flight Compartment Furnishing

1.5 Reason:

This Service Bulletin informs about the installation of an alternative seat harness assembly.

1.6 Concurrent documents:

N/A

1.7 Approval Note:

The technical information contained in this document has been approved under the authority of JAA Design Organisation Approval No. LBA.NJA.008.

G115; G115A; G115B; G115C



1.8 Accomplishment / Instructions

The Seat Belt Assembly FAG 7H-O/FAG 7D-O is no longer available. Aircraft equipped with Seat Belt Assembly FAG 7H-O/FAG 7D-O may alternatively be equipped with seat harness assembly SCHROTH 4-01-065401 or GADRINGER shoulder harness 5202 and lap harness 2700.

1.9 Repetitive Actions

N/A

1.10 Mass (Weight) and CG:

negligible

II. PLANNING INFORMATION

2.1 Material & Availability:

Please direct your inquiries or Purchase Orders for Seat Belt Assemblies as per 1.8 to GROB Product Support.

2.2 Special Tools:

N/A

2.3 Labour costs:

Modification: 2.0 hours

2.4 Reference documents:

Maintenance Manual,
Illustrated Parts Catalogue

2.5 Credit:

N/A

G115; G115A; G115B; G115C



III. REMARKS

- 3.1 The installation may be performed by a qualified person / an authorised aviation workshop and has to be certified in the logbook by an authorised inspector.
- 3.2 The Illustrated Parts Catalogue will be amended with the next revision.
- 3.3 If you have sold your aircraft in the meantime, would you kindly pass this information on to the new owner and forward his address and aircraft S/N to us.
- 3.4 For questions and assistance please contact:

Michael Reinhold, Product Support,
phone: +49 (08268) 998 105
fax: +49 (08268) 998 200
e-mail: m.reinhold@grob-aerospace.de