

## SERVICE BULLETIN NO. MSB10781-144/9

### I. TECHNICAL DETAILS

#### 1.1 Category:

Mandatory

**Note:** GROB issues Service Bulletins of category Mandatory (MSBs), if the information or instructions have a precautionary or safety intent either related to design or conformity and to publish revisions of manuals (AFM, AMM, IPC). However, according to Article 20 (1) of Regulation (EC) No. 216/2008, only EASA may issue mandatory information, in the form of an Airworthiness Directive (AD), in order to react to a given safety problem. Service Bulletins classified Mandatory issued by GROB's design organisation do not have a legally mandatory character equivalent to an AD, cannot have enforcement implications and, therefore, serve as information or instruction by GROB only. This also applies to cases where a Service Bulletin is published in anticipation of an AD.

#### 1.2 Airplanes affected:

G 115C, C1, C2, D, D2      S/N 82001-82084

#### 1.3 Time of Compliance:

Item 1.8.1:      Immediately after receipt of this Service Bulletin

Item 1.8.2:      After receipt of new issue / revised pages

#### 1.4 Subject:

ATA-Code:      N/A

Revision of the aircraft documentation. Information about revision status.

#### 1.5 Reason:

This Service Bulletin informs about the current revision status of the Flight Manual / Maintenance Manual / Illustrated Parts Catalogue of the GROB G 115C, G 115D models. Future documentation changes will be published under MSB 1078-144, followed by /sequence number.

#### 1.6 Concurrent documents:

-

#### 1.7 Approval Note:

The technical content of this document is approved under the authority of EASA Design Organization Approval No. EASA.21J.030.

These information or instructions relate to change no. MÄM 1078-196 which has been approved by the Authority (EASA) under approval no. 10057969.

**1.8 Accomplishment/ Instructions**

- 1.8.1 Check aircraft documentation for correct issue and revision status in accordance with the list below.
- 1.8.2 Incorporate latest revisions into the respective Manual

<b>G 115C, G 115D</b>	<b>Deutsche Ausgabe</b>	<b>English Issue</b>
<b>Flughandbuch Flight Manual</b> <b>C</b>	Revision 6, 15. September 1997	Revision 6, 15. September 1997
<b>Flughandbuch Flight Manual</b> <b>C2</b>	Revision 3, 15. September 1997	Revision 5, 15. September 1997
<b>Flughandbuch Flight Manual</b> <b>D</b>	Revision 4, 15. September 1997	Revision 6, 15. September 1997 Optional Revision 7 10. November 1999 (see note)
<b>Flughandbuch Flight Manual</b> <b>D2</b>	Revision 6, 15. September 1997	Revision 11, 15. September 1997
<b>Wartungshandbuch Maintenance Manual</b>	N/A	Issue 3, Revision 8, <a href="#">15. November 2015</a>
<b>Ersatzteilkatalog Illustrated Parts Catalogue</b>	Ausgabe 1, Revision 8, <a href="#">07. Mai 2016</a>	Issue 1, Revision 8, <a href="#">07. May 2016</a>

**Note: Revision 7 (English Issue) to the Flight Manual G115D resulted from the optional installation of the "Cold Weather Kit". Depending on implementation, either the a.m. revision status or the previous revision status of the Flight Manual is possible. To eliminate this ambiguity, the next revision of the Flight Manual G115D will bring the Flight Manual to a common revision standard, regardless of aircraft modification standard.**

**1.9 Repetitive Actions**

N/A

## **II. PLANNING INFORMATION**

### **2.1 Weight and CG**

N/A

### **2.2 Material and Availability**

All necessary revision pages for the affected manuals may be requested from GROB Product Support.

### **2.3 Special Tools**

N/A

### **2.4 Labor costs**

N/A

### **2.5 Reference documents**

see table above

### **2.6 Credit**

N/A

## **III. REMARKS**

The instructions in paragraph 1.8 have to be accomplished and certified in the logbook by authorized staff:

- in EASA countries according to Article 5 VO EG 2042/03 (VO EG 1056/2008) Appendix III – Part 66
- in non-EASA countries according to national regulations with respect to maintenance.

If you have sold your aircraft in the meantime, we kindly ask you to forward this information to the new owner and to provide us with the name and address of the new owner as well as with the respective serial number.

For questions and assistance please contact:

Product Support,  
phone: +49 8268 998105  
fax: +49 8268 998200  
e-mail: [productsupport@grob-aircraft.com](mailto:productsupport@grob-aircraft.com)