



SERVICE LETTER NO. SL115-48

I. TECHNICAL DETAILS

1.1 Category:

Optional

1.2 Airplanes affected:

G 115, G 115A, G 115B	all S/N
G 115C, G 115C2	all S/N

1.3 Time of Compliance:

during replacement of electrical fuel pump

1.4 Subject:

ATA-Code: 28-20 Fuel distribution

1.5 Reason:

The electrical fuel pumps had been re-designed by the manufacturer to become more efficient and to exceed performance and life requirements.

1.6 Concurrent documents:

N/A

1.7 Accomplishment/ Instruction

Replace the electrical fuel pump according to Maintenance Manual Chapter 28-20.

G 115 series



1.8 Repetitive Actions

N/A

1.9 Mass (Weight) and CG:

N/A

II. PLANNING INFORMATION

2.1 Material & Availability:

P/N new	P/N old	Name	Qty.	Applicable
40007E	40007	Electrical Fuel Pump (12V)	1	G 115, G 115A, G115B
476088E	476088	Electrical Fuel Pump (24V)	1	G 115C, G 115C2

2.2 Special Tools:

N/A

2.3 Labour costs:

Replacement: 1,0 hour

2.4 Reference documents:

Illustrated Parts Catalogue G 115A/B, Chapter 28-20
Illustrated Parts Catalogue G 115C/D, Chapter 28-20

2.5 Credit:

N/A



III. REMARKS

- 3.1** The modification may be performed by an authorised aviation workshop and has to be certified in the logbook by an authorised inspector.
- 3.2** If you have sold your aircraft in the meantime, would you kindly pass this information on to the new owner and forward his address and aircraft S/N to us.
- 3.3** For questions and assistance please contact:

Rudi Vodermeier , Head of Product Support,
phone: +49 8268 998139
fax: +49 8268 998200
e-mail: productsupport@grob-aerospace.de