

List of Service Bulletins



Type: **G 120TP**

Ref. TCDS No.: **EASA.A.565**

Plot Filter: **distributed**

List State: **4-Jul-2024**

SB No. / Issue	Title	Category				Affected Models / Serial numbers				Issue date	Associated Change Note	Remarks	
		Alert	Mandatory	Recommended	Optional	G 120TP-A							Serialnumbers
MSB 565-001/40	Aircraft Documentation Status		X			X				S/N 11001 on	24-Apr-2024	OCN 565-107	
RSB 565-002	Activation of ADS-B out capability			X		X				S/N 11002-11005 and 11020-11023	22-Jul-2013	MÂM 565-006	
MSB 565-003	Replacement of Nav/Position/Strobe Lights		X			X				S/N 11002-11005	5-Jul-2013	MÂM 565-009	
MSB 565-004	Replacement of CAWS Display Unit		X			X				S/N 11002-11005 and 11020-11023	28-Aug-2013	MÂM 565-027	
MSB 565-005	Replacement of the rear end sealing on the trim Bowden cable		X			X				S/N 11002-11017 and 11020-11024	26-Aug-2013	MÂM 565-029	
RSB 565-006	Installation of Improved Fuel Pressure Sensor			X		X				S/N 11002-11023	18-Sep-2013	MÂM 565-032	
MSB 565-007	Inspection of Rudder Pedal Adjustment		X			X				S/N 11002-11011 and 11020-11023	7-Oct-2013	MÂM 565-036	
RSB 565-008	Installation of additional Placards			X		X				S/N 11002-11009 and 11020-11023	26-Nov-2013	MÂM 565-020 MÂM 565-035	
MSB 565-009/1	Inspection or replacement of NLG Down-lock Mechanism		X			X				S/N 11002-11015 and 11020-11023	7-Apr-2014	MÂM 565-042	Special Inspection including Terminating Action
OSB 565-010	Installation of optional Power Reduction System				X	X					31-Mar-2014	OÂM 565-014	
RSB 565-011	Software Update of Garmin GTN			X		X				S/N 11002-11015 and 11020-11023	28-Mar-2014	MÂM 565-061	
RSB 565-012	Modification of Fuel Transfer System			X		X				S/N 11002-11015 and 11020-11024	25-Apr-2014	MÂM 565-051 MÂM 565-067	
RSB 565-013	Improved Condition lever cam-plate			X		X				S/N 11002-11036	5-Sep-2014	MÂM 565-065	
RSB 565-014	Improved FDR Resistor board			X		X				S/N 11002-11011 and 11020-11023	16-Apr-2014	MÂM 565-091	
MSB 565-015/1	Inspection of Rudder Lever Unit		X			X				S/N 11002-11023	13-Oct-2014	-	Special Inspection with Terminating Action RI 565-006
MSB 565-016	Inspection of Magnetic Transducer Accessory		X			X				S/N 11002-11024	28-May-2014	-	Special Inspection including Termination Action
OSB 565-018	Increased Maximum Landing Weight				X	X				S/N 11002-11036	2-Sep-2015	MÂM 565-100	RI 565-013 for aircraft modification
RSB 565-019	Alternative Turn & Slip Indicator			X		X				S/N 11002-11023	1-Oct-2014	OÂM 565-34	
RSB 565-021/1	Improvement of Continued Ignition indication			X		X				S/N 11002-11023	6-Oct-2014	MÂM 565-107	
RSB 565-023/1	Alternative Altimeter			X		X				S/N 11002-11036	18-Jun-2015	OÂM 565-35	
RSB 565-024	Additional Hydraulic Hose bracket			X		X				S/N 11002-11011 and 11020-11023	29-Sep-2014	MÂM 565-041	
RSB 565-025	Modified Main Wheel Axle			X		X				S/N 11002-11041	30-Sep-2014	MÂM 565-138	
MSB 565-026	Inspection of Cable Routing		X			X				S/N 11002-11031	4-Feb-2015	MÂM 565-202	Special Inspection including rectification
RSB 565-027	Modification of NLG doors			X		X				S/N 11002-11049	12-Feb-2015	MÂM 565-203	

List of Service Bulletins



Type: **G 120TP**
 Plot Filter: **distributed**

Ref. TCDS No.: **EASA.A.565**
 List State: **4-Jul-2024**

SB No. / Issue	Title	Category				Affected Models / Serial numbers				Issue date	Associated Change Note	Remarks	
		Alert	Mandatory	Recommended	Optional	G 120TP-A							Serialnumbers
RSB 565-028	Installation of Additional Seal in Oil Tank			X		X				S/N 11002-11050	5-Mar-2015	MÂM 565-218	
RSB 565-029/1	Modification of Hose attachment			X		X				S/N 11002-11054	30-Mar-2017	MÂM 565-128 MÂM 565-271	
RSB 565-030	Firmware and Software Update and New Parameter File for FDR			X		X				S/N 11002-11059	21-Sep-2015	MÂM 565-175, MÂM 565-190, MÂM 565-273	
MSB 565-031	Check of Aerobatics Placard		X			X				S/N 11002-11038	7-Apr-2015	-	Special Inspection including Termination Action
RSB 565-032	Modification of Collector Tank Vent Line			X		X				S/N 11002-11023 and 11031-11036	24-Apr-2015	MÂM 565-089	
RSB 565-033	Update of DAU			X		X				S/N 11024, 11037-11050	29-Apr-2015	MÂM 565-239	
MSB 565-034	Update of Garmin XPDR		X			X				S/N 11002-11036, excl 11024	6-Jul-2015	MÂM 565-246	
OSB 565-035/3	Gear Down Light				X	X				all S/N, without OÂM 565-017 (Digital Cockpit)	9-Dec-2016	OÂM 565-48	
OSB 565-036	Additional Hydraulic Pressure Gauge				X	X				S/N 11002-11036	18-May-2015	OÂM 565-50	
MSB 565-037	Correction of N2 RPM range markings (analog)		X			X				S/N 11001-11036, excl. 11024	11-Jan-2016	MÂM 565-258, MÂM 565-329	
RSB 565-038/1	Cowling support pads			X		X				S/N 11002-11054	25-Aug-2015	MÂM 565-236	
RSB 565-039	Safety wiring of the electrical connectors at the J-1 smart connector			X		X				S/N 11024, 11037-11060	8-Jun-2015	MÂM 565-259	
OSB 565-042/4	Gear Down Light				X	X				all S/N, equipped with OÂM 565-017 (Digital Cockpit)	27-Apr-2023	OÂM 565-49, MCN 565-377, MCN 565-395, MCN 565-417, MCN 565-907	
RSB 565-043/1	Modification of Nose Wheel Steering			X		X				S/N 11002-11045	17-May-2017	MÂM 565-145 MÂM 565-241	
OSB 565-044	Modification of Myanmar color scheme				X	X				S/N 11037, 11038, 11048-11050	7-Oct-2015	MÂM 565-260	
RSB 565-045	Modification of Condenser Inlet Duct			X		X				S/N 11002-11023, 11025-11082	26-Oct-2015	MÂM 565-291	RI 565-017 for aircraft modification
RSB 565-046	Update of EICAS.dat			X		X				all S/N, equipped with OÂM 565-017 (Digital Cockpit)	2-Nov-2015	MÂM 565-291	Introduced in Series Production from S/N 11060

List of Service Bulletins



Type: **G 120TP**

Ref. TCDS No.: **EASA.A.565**

Plot Filter: **distributed**

List State: **4-Jul-2024**

SB No. / Issue	Title	Category				Affected Models / Serial numbers				Issue date	Associated Change Note	Remarks	
		Alert	Mandatory	Recommended	Optional	G 120TP-A							Serialnumbers
MSB 565-047	Correction of N2 RPM range markings (digital)		X			X				S/N 11037-11074	11-Jan-2016	MAM 565-329	
MSB 565-048/2	One-time inspection of Rudder cable lead-through		X			X				S/N 11002-11070	25-Apr-2016	-	RI 565-018 for aircraft modification
RSB 565-050	Modification of drag strut cylinder			X		X				S/N 11002-11074	11-Jan-2016	MAM 565-325	
MSB 565-051/3	Inspection of flap interconnect cable		X			X				S/N 11001-11081	25-Apr-2016	-	RI 565-019 and RI 565-020 for aircraft modification
RSB 565-052/1	Improved Fuel Pump			X		X				S/N 11002-11081	23-Aug-2016	MAM 565-321	
RSB 565-053	DAU Maintenance Switch			X		X				S/N 11037-11081	14-Apr-2016	MCN 565-371	
RSB 565-054	Additional means for electrical system isolation			X		X				S/N 11002-11098 and S/N 11101-11110 except 11099 and 11100	20-Nov-2020	MCN565-444a MAM565-127	
RSB 565-055/1	Check of engine frame for tensionless installation			X		X				S/N 11002-11116	16-Aug-2016	-	
RSB 565-056/4	Replacement of Orings in Oil vent overpressure valves			X		X				S/N 11002-11091, 11099-11153	10-Jan-2018	MCN 565-397 MCN 565-607	
MSB 565-057	Replacement of RAD ALT Circuit Breaker		X			X				S/N 11037-11082, 11085	15-Apr-2016	MCN 565-403	
RSB 565-058	New evaporator blower motors			X		X				S/N 11002-11098	18-Apr-2016	MCN 565-352	
OSB 565-059	Protection foil for wing and stabiliser leading edge				X	X				all	14-Feb-2017	OCN 565-67 MCN 565-479	
MSB 565-060	Hole in oil cooler air duct		X			X				S/N 11082-11086	28-Apr-2016	MCN 565-413	
RSB 565-061/1	Installation of hydraulic pressure sequence valve			X		X				S/N 11001-11091	12-May-2016	MAM 565-340	
RSB 565-064	Non-metallic pulleys for rudder control system			X		X				S/N 11001-11097	23-May-2016	MCN 565-411	
RSB 565-068	Protective cover for emergency hammer			X		X				S/N 11082-11110	29-Sep-2016	MCN 565-429	
MSB 565-069/2	MLG drag strut		X			X				S/N 11001-11109	22-Nov-2016	MCN 565-480 MCN 565-522	
RSB 565-070	New aircraft towing placard			X		X				S/N 11002-11101	16-Nov-2016	MCN 565-504	
MSB 565-071	New nose wheel for Beringer landing gear		X			X				S/N 11082-11096, 11098, 11101	30-Nov-2016	MCN 565-501	
OSB 565-072/3	Retrofit of improved FDR V3				X	X				all equipped with OAM 565-22	29-Oct-2018	OCN 565-73	
OSB 565-073/2	Installation of Video Recording System				X	X				all equipped with OAM 565-22	7-Apr-2017	OCN 565-60 OCN 565-71	
OSB 565-074/1	Update of EFIS Software 8.0E				X	X				S/N 11037-11096 and 11098-11101	4-Apr-2017	MCN 565-394	
OSB 565-075	Installation of FDR Cockpit Area Mic				X	X				all equipped with OAM 565-22	3-Feb-2017	OCN 565-58	
RSB 565-076	Modified Oil Vent Overpressure Valve			X		X				S/N 11002-11139	27-Feb-2017	MCN 565-529	

List of Service Bulletins

Type: **G 120TP**
 Plot Filter: **distributed**

Ref. TCDS No.: **EASA.A.565**
 List State: **4-Jul-2024**



SB No. / Issue	Title	Category				Affected Models / Serial numbers				Issue date	Associated Change Note	Remarks	
		Alert	Mandatory	Recommended	Optional	G 120TP-A							Serialnumbers
MSB 565-077	Additional clamp for bleed air cable		X			X				S/N 11002-11124	6-Mar-2017	MCN 565-531	
MSB 565-078/2	Exchange of Control Grip		X			X				S/N 11092-11097, 11102-11110, 11114	21-Nov-2018	MCN 565-488	
OSB 565-080	Activation of Round Dials				X	X				all S/N with EFIS software 8.0E	22-Mar-2017	OCN 565-77	
RSB 565-081/3	Improved front bearing assy MLG			X		X				S/N 11001-11129	11-Apr-2017	MCN 565-527 MCN 565-561 MCN 565-587	
RSB 565-082	Backshell Change of Cable Loom 14VB			X		X				S/N 11001-11087	13-Feb-2017	MCN 565-355	
MSB 565-083/1	Limitation of Aerobatic Operation		X			X					21-Feb-2017	MCN 565-554	
OSB 565-084/1	Alternative DME Antenna				X	X				all S/N, if not equipped with OCN 565-79 ex-works	11-May-2021	OCN 565-79	
OSB 565-085/1	Exchange of Dimmer Unit and Poti for Map Light				X	X				S/N 11001-11109, 11111-11113, 11117, 11118	24-Mar-2017	MCN 565-500	
RSB 565-086	Firmware Update JPI EDM 900			X		X				S/N 11002-11036, excl. 11024	24-Mar-2017	MCN 565-552	
MSB 565-088	Inspection of elevator control spring		X			X				11001-11103, 11111-11113, 11116	24-Apr-2017	-	
RSB 565-089/2	Battery Change			X		X				S/N 11001-11101 and 11104, 11105, 11111-11113, 11116	29-Aug-2017	MCN 565-567	
RSB 565-090	FDR V3 Firmware Update for 8Hz Recording Rate			X		X				S/N 11099, 11100, 11111-11113	17-Jul-2017	MCN 565-579a	
OSB 565-091	Fuel Tank Indication EMI Suppression				X	X				S/N 11099, 11100, 11111-11113, 11117, 11118	23-Jun-2017	MCN 565-593, OCN 565-87	
OSB 565-092/2	AMU Update for 5 Ohm Mic Impedance				X	X				all S/N equipped with 5 Ohm headsets	9-May-2019	OCN 565-65 MCN 565-745	
OSB 565-093/2	Additional Decals for optional Decor Scheme 53				X	X				all equipped with OAM 565-53	20-Aug-2020	MCN 565-589 MCN 565-756	
OSB 565-094/2	Increased Maximum Take-off Mass				X	X				all S/N without OCN 565-74	3-Sep-2018	OCN 565-74 MCN 565-711	

List of Service Bulletins



Type: **G 120TP**
 Plot Filter: **distributed**

Ref. TCDS No.: **EASA.A.565**
 List State: **4-Jul-2024**

SB No. / Issue	Title	Category				Affected Models / Serial numbers				Issue date	Associated Change Note	Remarks	
		Alert	Mandatory	Recommended	Optional	G 120TP-A							Serialnumbers
OSB 565-095/2	Speaker Panel with XLR Headset Sockets				X	X				S/N 11099, 11100, 11111-11113, 11117, 11118, 11122, 11123, 11127-11132, 11198-11200	27-Feb-2023	OCN 565-82	
OSB 565-096/4	XPDR with certified ADS-B Out				X	X				all S/N without OCN 565-83	15-May-2024	OCN 565-83 MCN 565-684	
RSB 565-097	Relocation of First Aid Kit			X		X				S/N 11002-11141	18-Jul-2017	MCN 565-590	
RSB 565-098	New Seal for Avionic Compartment Panels			X		X				S/N 11001-11129	6-Jun-2017	MCN 565-584	
RSB 565-099/1	Modification of CFRP Cowling			X		X				all S/N up to 11136, that are equipped with OCN 565-070	20-Feb-2019	MCN 565-608, MCN 565-603, MCN 565-589a	
RSB 565-101	Modified Oil Pressure Sense Line			X		X				S/N 11002-11116	7-Jul-2017	MCN 565-509	
OSB 565-102	Single Piece Canopy				X	X				all S/N without OSB 565-073	15-Sep-2017	OCN 565-69, OCN 565-84	
MSB 565-103/1	Sealed Connector of Current Sensor for Battery Relay		X			X				S/N 11002-11147	21-Mar-2018	MCN 565-626	
RSB 565-104	Installation of NO HOLD placard			X		X				S/N 11002-11133	6-Oct-2017	MCN 565-644	
OSB 565-105	EICAS Fuel Setting to KG				X	X				S/N 11099, 11100, 11111-11113, 11117, 11118, 11122, 11123, 11127, 11128	26-Jul-2017	OCN 565-89	
RSB 565-106	Installation of improved Video Recorder Software			X		X				All S/N equipped with OCN 565-60	4-Aug-2017	MCN 565-580	
MSB 565-107	Special Inspection of Rear Fuselage		X			X				all S/N up to 11147	19-Jan-2018	MCN 565-618	
RSB 565-108	Oxygen Filling Valve in Center Console			X		X				all S/N equipped with OÄM 565-07 up to 11147	1-Mar-2018	MCN 565-477	
MSB 565-109	Change Cotter Pins for Wheel Nuts (Parker)		X			X				11082-11112, 11114-11124, 11127, 11128	8-Sep-2017	MCN 565-000	
RSB 565-110/1	Easy Access Wheel Cover (Parker)			X		X				All S/N equipped with Parker Wheels up to S/N 11141	3-Aug-2023	MCN 565-628a	

List of Service Bulletins

Type: **G 120TP**
 Plot Filter: **distributed**

Ref. TCDS No.: **EASA.A.565**
 List State: **4-Jul-2024**



SB No. / Issue	Title	Category				Affected Models / Serial numbers				Issue date	Associated Change Note	Remarks	
		Alert	Mandatory	Recommended	Optional	G 120TP-A							Serialnumbers
OSB 565-111	Relocation of the AFM Container				X	X				all S/N without OCN 565-84	15-Sep-2017	OCN 565-84	
OSB 565-112/5	Update of EFIS Software 8.0F				X	X				all S/N with OAM 565-17	16-Jul-2020	MCN 565-625b, MCN 565-706	
OSB 565-113	Speaker Panel with Insulated Headset Sockets				X	X				11083-11091	5-Oct-2017	MCN 565-491a, RI-565-037	
MSB 565-114/2	Installation of Fuselage Reinforcement		X			X				11002-11101, 11103-11108, 11111-11113, 11116-11118, 11122, 11123, 11125-11132, 11134-11147	19-Jul-2018	MCN 565-618a	
RSB 565-116/2	Modified NAV Light-Unit for Horizontal Stabilizer			X						all S/N up to 11147	12-Jul-2019	MCN 565-656	
RSB 565-117/2	Modified NAV Light-Unit for Winglet			X		X				all S/N up to 11147	29-Jan-2020	MCN 565-657	
MSB 565-118/1	Exchange of Non-Conforming Lock-Washers		X			X				11002-11101, 11103-11108, 11111-11113, 11116-11118, 11122, 11123, 11125-11132, 11134-11141	6-Feb-2018	-	
MSB 565-119/2	Deactivation of GPS input for Becker XPDR		X			X				11092-11101, 11103-11108, 11111-11113, 11116-11118, 11122, 11123, 11125-11132, 11137, 11138, 11142-11145	5-Mar-2018	MCN 565-687a	
RSB 565-120	Screw Locking for Control Grips			X		X				all S/N up to 11164	27-Feb-2018	MCN 565-678	
RSB 565-121	Safety Wire for GCU Connector			X		X				all S/N up to 11144	6-Mar-2018	MCN 565-682	
MSB 565-122/2	Special Inspection of Pedal Adjustment Bracket		X			X				11002-11101, 11103-11108, 11111-11113, 11116-11118, 11122-11132, 11134-11147	26-Jul-2018	MCN 565-686a	

List of Service Bulletins

Type: **G 120TP**
 Plot Filter: **distributed**

Ref. TCDS No.: **EASA.A.565**
 List State: **4-Jul-2024**



SB No. / Issue	Title	Category				Affected Models / Serial numbers				Issue date	Associated Change Note	Remarks	
		Alert	Mandatory	Recommended	Optional	G 120TP-A							Serialnumbers
OSB 565-123	CFRP I-Panel Cover				X	X				all S/N with OÄM 565-17	6-Jun-2019	OCN 565-81	
MSB 565-124	CAS Mute Switch		X			X				11037-11118, 11122-11132, 11137, 11138, 11142-11147	5-Jul-2019	MCN 565-692	
RSB 565-126	Modification of Seat Locking Mechanism			X		X				all S/N up to 11158	26-Apr-2018	MCN 565-701	
MSB 565-127/2	Special Inspection of Fuselage		X			X				S/N 11002-11118, 11122-11132, 11134-11147	1-Jul-2021	-	
MSB 565-130	Inspection of Fuel Control Unit		X			X				all S/N	23-Jul-2018	MCN 565-708	Rolls-Royce CEB-73-2041, Honeywell Service Bulletin GT-73-0397
RSB 565-131	Alternative crotch straps			X		X				11002-11179	11-Jun-2018	MCN 565-702a	
MSB 565-132/1	NLG uplock		X			X				From S/N 11037 on	13-Aug-2018	MCN 565-110	
MSB 565-133	Reduction of NLG tire pressure		X			X				all S/N with OCN 565-074 or OSB 565-094	16-Aug-2018	MCN 565-711	
MSB 565-134/1	Replacement of ADAHRS Mod 4 or Mod 5		X			X				S/N 11037-11165 equipped with OÄM 565-017 (Digital Cockpit)	26-Jan-2023	MCN 565-677 MCN 565-826	
OSB 565-135	Installation of original EICAS for 8.0E				X	X					21-Sep-2018	MCN 565-394 OCN 565-87	
MSB 565-136/2	Lightning protection inspection of the elevator assy		X			X				S/N 11001-11118, 11122-11132, 11134-11147	11-Dec-2019	MCN 565-723	
RSB 565-137	Horizontal Installation of Main Fuel Pumps			X		X				up to S/N 11117	10-Dec-2018	MÄM 565-433	
RSB 565-138	Modified tubing for FDR			X		X					10-Jan-2019	MCN 565-422	
RSB 565-140/1	Additional bonding of fuel vent line			X		X				S/N 11001-11118, 11122-11132, 11134-11147	31-Jul-2020	MCN 565-743	

List of Service Bulletins



Type: **G 120TP**
 Plot Filter: **distributed**

Ref. TCDS No.: **EASA.A.565**
 List State: **4-Jul-2024**

SB No. / Issue	Title	Category				Affected Models / Serial numbers				Issue date	Associated Change Note	Remarks	
		Alert	Mandatory	Recommended	Optional	G 120TP-A							Serialnumbers
OSB 565-141/3	Optional FLARM system				X	X				S/N 11099, 11100, 11111-11113, 11117, 11118, 11122, 11123, 11127-11132, 11137, 11138, 11142-11147	6-Nov-2019	OCN 565-94	
OSB 565-142/1	Optional AUX Power Connector in Cockpit				X	X				from S/N 11099 except S/N 11101, 11104-11107	19-Aug-2019	OÄM 565-55	
OSB 565-143	Additional Decor for Color Scheme ETAF				X	X				all S/N equipped with OCN 565-95	29-Aug-2019	OCN 565-96 MCN 565-760	
RSB 565-144	Alternative Dome Light for Two Piece Canopy			X		X				all S/N without OCN 565-69	17-Sep-2019	MCN 565-718	
RSB 565-145	New material for gearbox ventilation hose			X		X				S/N 11001-11189	20-Mar-2020	MCN 565-772	
RSB 565-146/1	Modified fuel pump			X		X				11099-11100, 11111-11113, 11117-11118, 11122-11123, 11127-11132, 11137-11138, 11142-11147	15-Jun-2020	MCN 565-778	
MSB 565-147	Special Inspection of Rudder Cable		X			X				all S/N, without OÄM 565-01	23-Jun-2020	-	
MSB 565-148	Fairlead Installation for Rudder Cable		X			X				S/N 11001 thru 11189	24-Jul-2020	MCN 565-791	
OSB 565-149	Application of Decals for Color Scheme 98				X	X				all S/N with OCN 565-98	14-Dec-2020	OCN 565-98	
OSB 565-150	TOT and TRQ exceedance Warning				X	X				all S/N with EFIS software 8.0E	15-Dec-2020	OCN 565-102	
RSB 565-151	ESI-500 as replacement for ESI-2000			X		X				all S/N with OÄM 565-17	20-Jul-2022	MCN 565-786	
RSB 565-152	Replacement of Landing- and Taxi-Light			X		X				from S/N 11001-11183	29-Oct-2020	MCN 565-774	
MSB 565-153	Bonding of control stick unit and flap drive assy		X			X				S/N 11001-11118, 11122-11132, 11134-11147	13-Oct-2023	MCN 565-743	

List of Service Bulletins

Type: **G 120TP**
 Plot Filter: **distributed**

Ref. TCDS No.: **EASA.A.565**
 List State: **4-Jul-2024**



SB No. / Issue	Title	Category				Affected Models / Serial numbers				Issue date	Associated Change Note	Remarks	
		Alert	Mandatory	Recommended	Optional	G 120TP-A							Serialnumbers
MSB 565-154/3	Life limit for NLG drag strut		X			X				from S/N 11001-11189	6-Sep-2022		
RSB 565-155/2	Modification of NLG Drag Strut			X		X				from S/N 11001-11189	22-Mar-2022	MCN 565-813 MCN 565-836	
RSB 565-156/1	Drain channel for cowling CFRP and GFRP			X		X				all S/N with cowling doors	10-Jan-2023	MCN 565-849	
RSB 565-157/2	Update of EFIS Software 9.0A Minor Mod3			X		X				S/N all as affected equipped with OÄM 565-017 (Digital cockpit)	3-Nov-2023	MCN 565-863	
RSB 565-158	FDR V3 Firmware Update for MDPS			X		X				from S/N 11149-11189 with OÄM 565-22 and OCN 565-60 including MCN 565-785	10-Nov-2021	MCN 565-821	
MSB 565-159/1	Life limit for MLG downlock spring		X			X				all S/N	6-Sep-2022	-	
RSB 565-160	Exchange of bowden cable support bracket on pilot seat			X		X				all S/N as affected	22-Nov-2021	-	
RSB 565-161	Alternative Emergency Flashlight			X		X				S/N 11001-11159,11164-11189	20-Dec-2021	MCN 565-787	
MSB 565-162/1	Restriction of Autopilot VS Mode		X			X				all S/N equipped with Autopilot (OÄM 565-023) and EFIS software version 9.0A (MCN 565-789 or RSB 565-157 initial issue)	15-Jul-2022	-	Terminating Action RSB 565-157/1 or later
RSB 565-163	Oil hose chafing by forward LH cowling door hinge stud bolts			X		X				all S/N with cowling doors up to S/N 11202	25-Jul-2022	MCN 565-864	
MSB 565-165	Installation of IDU-680 MOD2		X			X				all S/N up to 11197 equipped with OÄM 565-017 (Digital Cockpit)	28-Jul-2022	MCN 565-790	
MSB 565-166	Inspection of elevator control spring		X			X				all Serial Number	5-Aug-2022	-	

List of Service Bulletins

Type: **G 120TP**
 Plot Filter: **distributed**

Ref. TCDS No.: **EASA.A.565**
 List State: **4-Jul-2024**



SB No. / Issue	Title	Category				Affected Models / Serial numbers				Issue date	Associated Change Note	Remarks	
		Alert	Mandatory	Recommended	Optional	G 120TP-A							Serialnumbers
RSB 565-167/1	Change of NAV/COM power supply			X		X				all S/N up to 11197 with OÄM 565-017 (Digital Cockpit) and S/N 11201-11204	22-Mar-2023	MCN 565-873	
MSB 565-168	Shear force bolt sleeve		X			X				S/N 11001-11189	15-Jun-2023	MCN 565-875	
RSB 565-171	Alternative NAV/COM			X		X				all S/N up to 11204 equipped with OÄM 565-017 (Digital Cockpit)	17-Nov-2022	MCN 565-797	
RSB 565-173	New Flight Guidance Computer (Genesys AP)			X		X					4-Dec-2023	MCN 565-814	All S/N up to S/N 11195 equipped with optional autopilot (OÄM 565-23)
OSB 565-174/3	Rear View Mirror				X	X				S/N all as affected up to S/N 11197	7-May-2024	OCN 565-101	
MSB 565-175	Special Inspection of Brake Fluid Reservoir		X			X				S/N 11192-11197	5-Dec-2022	-	
MSB 565-176	Traffic Inhibit Switch change dimmable to Day / Night		X			X				S/N 11196-11204 with MCN 565-814 (New Flight Guidance Computer)	9-Dec-2022	MCN 565-895	
RSB 565-177	FDR V2 firmware update SL0028			X		X				S/N 11001-11107, except 11099, 11100, 11102, 11103	26-May-2023	MCN 565-902	S/N 11001-11107, except S/N 11099, 11100, 11102, 11103
RSB 565-178/1	Reinforcement of the CFRP Cowling			X		X				S/N 11198-11204	9-Mar-2023	MCN 565-900	
RSB 565-179/1	Improvement of Reduced Power Stop (Option 14)			X		X				all S/N as affected equipped with Option 14 (reduced power)	21-Apr-2023	MCN 565-918	
RSB 565-179/2	Improvement of Reduced Power Stop (Option 14)			X		X				11102-11204 equipped with Option 14 (reduced power)	19-Jul-2023	MCN 565-918	11102-11204 equipped with Option 14 (reduced power)

List of Service Bulletins



Type: **G 120TP**
 Plot Filter: **distributed**

Ref. TCDS No.: **EASA.A.565**
 List State: **4-Jul-2024**

SB No. / Issue	Title	Category				Affected Models / Serial numbers				Issue date	Associated Change Note	Remarks	
		Alert	Mandatory	Recommended	Optional	G 120TP-A							Serialnumbers
RSB 565-180/1	Relocation of Radar Altimeter antenna			X		X				all S/Ns up to S/N 11208 and S/N 11211 through S/N 11213 equipped with Radar Altimeter (OÄM 565-24) and Carbon-flaps (OCN 565-117).	17-May-2024	MCN 565-927	
RSB 565-181	Modification of the Pitot_Static Tube hose attachment			X		X				S/N 11001-11204	29-Mar-2023	MCN 565-882	
OSB 565-183/1	Change Audio Unit settings to 150 Ohm high impedance microphones				X	X				all S/N equipped with OCN565-65 or OSB565-92	13-Sep-2023	OÄM 565-17	
OSB 565-184/1	Application of Decals for Color Scheme Option 110				X	X				all S/N with OCN 565-110	21-Mar-2023	OCN 565-110	
MSB 565-185	Scrapping of Trim Tabs		X			X				SN 11187,11190,11198, 11202	22-Jun-2023	-	
RSB 565-186	TAS processor replacement			X		X				all S/N with OÄM 565-21	13-Jul-2023	MCN 565-796	
OSB 565-188	Reshaped singlepiece window (Canopy Sweden)				X	X				all S/N except 11092-11097 and 11116	21-Jul-2023	OCN 565-119	
MSB 565-190	Replacement of bushings on elevator control middle idler-lever		X			X				11002-11204	13-Dec-2023	MCN 565-941	11002-11204
OSB 565-195/2	Installation of TKS System				X	X				11198-11200, 11205-11208, 11211-11213	18-Jun-2024	OCN 565-107, OCN 565-111	
RSB 565-197	Modification of Nose Landing gear uplock hook			X		X				11001-11213	23-Apr-2024	MCN 565-997	
RSB 565-199	Adjustment of Audio Settings for GDR			X		X				all S/Ns up to S/N 11208 and S/N 11211 through S/N 11213 equipped with New VHF NAV/COM GDR-1636 (MCN 565-797).	15-May-2024	MCN 565-1006	

List of Service Bulletins



Type: **G 120TP**
 Plot Filter: **distributed**

Ref. TCDS No.: **EASA.A.565**
 List State: **4-Jul-2024**

SB No. / Issue	Title	Category				Affected Models / Serial numbers				Serialnumbers	Issue date	Associated Change Note	Remarks
		Alert	Mandatory	Recommended	Optional	G 120TP-A							
OSB 565-200	Adjustment of Audio Warning Volume				X	X				All S/Ns equipped with OAM 565-17 (Digital Cockpit) and EFIS software 9.0A (MCN 565-789) or later software versions.	23-May-2024	MCN 565-1006	
MSB 565-203	Canopy jettison system		X			X				11001-11154; 11164-11189		MCN 565-869	