	<b>Service Letter 115-12</b>	<b>GROB G 115E</b>
---	----------------------------------	------------------------

**Subject:** Change of Engine Power Control Panel Cover Plate P/N 115E-7000.27E

**Models Affected:** G 115E, all aircraft up to S/N 82132

**Time of Compliance:** next 50 hours inspection after receipt of parts

**Background Information:** The Engine Power Control Panel Cover Plate, presently made of aluminium with a rear cover of leather, will be replaced by a Cover Plate made from plastic material to reduce possible wear on the Engine Control Levers.

**Action:**


1. Remove Control Lever Knobs IAW Maintenance Manual chapter 76-10
2. Remove Cover Plate from Centre Console .
3. Insert and fasten new Cover Plate P/N 115E-7000.27E
4. Install Control Lever Knobs on throttle lever, mixture control lever and propeller control lever with self locking nuts P/N LN9348M6.
5. Check the engine control levers for full range of movement and that they reach the end stops and do not touch the cut-outs of the Cover-Plate.

**Material:** The Cover Plate P/N 115E 7000.27E and 3 nuts P/N LN9348M6 will be supplied by Grob .

**Weight and Balance:** not affected

**Remarks:** The Illustrated Parts Catalogue will be amended with the next revision.

DATUM DATE	ERSETZT AUSGABE REPLACES ISSUE	BEARBEITET VON PREPARED BY	MUSTERGEPRÜFT APPROVED	SEITE PAGE
18.10.2000	29.08.2000	M. Reinhold		1 of 2

	<b>Service Letter 115-12</b>	<b>GROB G 115E</b>
---	----------------------------------	------------------------

**Contact:** For questions and assistance please contact:  
Rudi Vodermeier , Product Support,  
phone: +49 8268 998139  
fax: +49 8268 998200

Mattsies, 18. October 2000

Dipl.Ing. (FH) H. Micheler  
(Manager Airworthiness/ Certification)

DATUM DATE	ERSETZT AUSGABE REPLACES ISSUE	BEARBEITET VON PREPARED BY	MUSTERGEPRÜFT APPROVED	SEITE PAGE
18.10.2000	29.08.2000	M. Reinhold		2 of 2