

 GROB LUFT UND RAUMFAHRT	Service Letter 115-18	GROB G 115C/D
--	--	--------------------------------

Subject: NLG bracket

Models Affected: G 115C/D, all S/N

Time of Compliance: optional

Background Information: The design of the NLG bracket P/N 115C-5219 was improved and the redesigned bracket P/N 115C-5240 is offered as an optional replacement.

Action: The NLG bracket P/N 115C-5219 may be replaced NLG bracket P/N 115C-5240 in combination with spherical ball P/N 115C-5200.10 IAW Maintenance Manual Chapter 32-20.

Material:

Name	P/N	Qty.	Remarks
NLG bracket	115C-5240	1	Substitutes P/N 115C-5219
Spherical bolt	115C-5200.10	1	Substitutes P/N 115C-5200.09

Tool: no special tool required

Weight and Balance: not affected

Remarks: The Illustrated Parts Catalogue will be amended during the next revision.

Contact: For questions and assistance please contact:

Rudi Vodermeier , Product Support,
 phone: +49 8268 998139
 fax: +49 8268 998200

Mattsies, 19 October 2000

Dipl.Ing. (FH) H. Micheler
 (Manager Airworthiness/ Certification)

DATUM DATE	ERSETZT AUSGABE REPLACES ISSUE	BEARBEITET VON PREPARED BY	MUSTERGEPRÜFT APPROVED	SEITE PAGE
19.10.2000		R. Vodermeier		1 of 1