



Subject: Updates to Flight Manual GROB G 109, edition March 1981 to revision date Oct. 1, 1981.

Effectivity: Motorglider GROB G 109, all serial numbers.

Reason: Flight experience with the first production airplane has shown the need to amend the flight manual prior to printing in some details.

Instructions: To update the flight manual to revision date Oct. 1, 1981 replace the following pages:

- Page 4 : Revision date Oct. 1, 1981.
- Page 10 : Notes to engine oil level, para. II. 4. 3. new.
- Page 34 : Addition to rudder deflection during take-off, para. III. 9 and Addition to prop setting during cruise flight, para. III. 10 new.
- Page 36a: Addition to airbrake system during landing, para. III. 14 new.
- Page 40 : Addition for take-offs under rain and with insect deposits, para. IV. 4. c. new.

Material: The amended pages 4, 10, 34, 36a and 40 can be ordered from the manufacturer.

Mattsies, Oct. 1, 1981  
gez. i. A. Dipl. Ing. H. Wilser

LBA approved:  
15.10.81  
.....