

List of Service Letters



Type: **G 115**
 Plot Filter: **approved**

Ref. TCDS No.: **EASA.A.364**
 List State: **24-Aug-2015**

SL No. / Issue	Title	Affected Models										Issue date	Remarks
		G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E	G 115EG	G 115TA		
115-1	Replacement of rear canopy locking pins								X			28-Mar-2000	S/N 82086 - 82116
115-2	Canopy lock								X			10-Apr-2000	S/N 82086 - 82119
115-3	Installation of a fastening strap for the fire extinguisher								X			3-May-2000	S/N 82086 - 82116
115-4	Installation of GPS antenna								X			18-May-2000	
115-5	Removal of lightning protection cable								X			25-May-2000	S/N 82086 - 82089
115-6	Exhaust attachment								X			13-Jun-2000	S/N 82086 - 82089
115-7	Replacement of propeller spacer						X					21-Jun-2000	
115-8	Modification of the spinner dome support								X			3-Jul-2000	
115-9	G - meter limits									X		18-Jul-2000	
115-10	Installation of a jumper to inhibit the semi-duplex mode								X			3-Aug-2000	
115-11	Introduction of a protection sheet to preclude inadvertent operation of the master switch								X			18-Oct-2000	
115-12	Change of Engine Power Control Panel Cover Plate								X			18-Oct-2000	up to S/N 82132
115-13	Seat Harness									X		29-Aug-2000	
115-14	Nose Wheel Axle Bush									X		24-Oct-2000	
115-15	Modification of flexible hoses								X			23-Oct-2000	S/N 82146-82149
115-16	Change of cable loom routing								X			13-Oct-2000	up to S/N 82141
115-17	Nose wheel fork				X	X	X	X				18-Oct-2000	
115-18	NLG bracket				X	X	X	X				19-Oct-2000	
115-19	Modification of the Oil Cooler Flexible Hose								X			6-Nov-2000	
115-20	Throttle Friction Adjuster								X			6-Nov-2000	
115-21	Repositioning of GPS antenna								X			22-May-2001	
115-22	Canopy Lock								X			24-Nov-2000	
115-23	Change of Oil Separator Brackets								X			28-Nov-2000	
115-24	Wheel Bearing Check									X		8-Dec-2000	
115-25	Manifold Pressure Gauge								X			11-Dec-2000	S/N 82150 - 82153
115-26	Modification of the fuel vent system				X	X	X	X				9-Jan-2001	
115-27	Introduction of a new Side Stay Pivot Bearing									X		5-Jan-2001	
115-28	Introduction of a new Paint Scheme (Trial Installation)								X			2-Feb-2001	S/N 82156 - 82157
115-29	Cable loom G 115E-21VB								X			2-Mar-2001	
115-30	Engine controls support bracket								X			20-Mar-2001	
115-31	Flexible Hoses								X			23-Mar-2001	S/N 82086-82145, 82150-82168
115-32	GRP Cut-Out								X			23-Apr-2001	

List of Service Letters



Type: **G 115**
 Plot Filter: **approved**

Ref. TCDS No.: **EASA.A.364**
 List State: **24-Aug-2015**

SL No. / Issue	Title	Affected Models										Issue date	Remarks	
		G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E	G 115EG	G 115TA			
115-33	Brake pedals							X	X				19-Apr-2001	
115-34	Battery retention								X				27-Apr-2001	
115-35	Copper gasket								X	X			10-May-2001	
115-36	Main wheel fairing								X	X			18-Jun-2001	
115-37	Fuel tank access sealant								X	X			29-Jun-2001	
115-38	Rudder actuator lever								X	X				
115-39	Instrument panel clearance								X				29-Jun-2001	
115-40	Wheel brake assy								X				1-Aug-2001	S/N 82103/E, 82127/E
115-41	Ignition switch								X				2-Aug-2001	S/N 82182/E - 82184/E
115-42	Main Gear Door Actuator rods										X		25-Feb-2002	
115-43	Flutter Damper								X	X			4-Jul-2002	
115-44	Installation of Wheel Brake Test Equipment								X				15-Jul-2002	S/N 82111, 82164
115-45/2	Nose landing gear								X	X			30-Mar-2006	
115-46	Engine Baffle								X	X			15-Nov-2002	
115-47	Nose wheel steering								X				18-Dec-2002	
115-48	Electrical Fuel pump	X	X	X	X	X							21-Jul-2003	
115-49	Canopy lock								X	X			12-Feb-2004	
115-50	Propeller RPM								X				10-Mar-2004	
115-51	Cockpit furnishing								X				17-Jun-2004	
115-52	Wheels and brakes				X	X	X	X	X	X			11-Dec-2007	
115-53	Torque Value								X				23-Jul-2010	
115-55	Engine driven fuel pump						X	X	X	X	X		24-Aug-2015	