

List of Service Bulletins



Type: **G 115**
 Plot Filter: **distributed**

Ref. TCDS No.: **EASA.A.364**
 List State: **23-May-2018**

SB No. / Issue	Title	Category				Affected Models								Issue date	Associated Change Note	Remarks		
		Alert	Mandatory	Recommended	Optional	G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E				G 115EG	G 115TA
1078-1	Installation of additional equipment, revision of Flight					X										24-Jun-1987		German language
1078-2/1	Installation of a spring device between aileron and					X										15-Jun-1988		
1078-3	Special equipment for export to the Netherlands					X										15-Jun-1988		
1078-4	Revision 3 of the Flight Manual G 115 (German Issue)					X										1-Jul-1988		German language
1078-5	Special equipment for export to the USA					X										16-Dec-1988		
1078-6	Approval of installation of a primer system					X										20-Dec-1988		
1078-7	Authorized installation of the SENSENICH prop					X										16-Dec-1988		
1078-8	Exchange of the bowden cables...					X										22-May-1989		
1078-9	Extension of operation limits, new edition of FM , inst.					X										24-Oct-1989		
1078-10	Design standard and special equipment for export to					X	X									28-Apr-1992		
1078-12/1	Cracks on main landing gear axles					X	X									4-Jul-1990		
1078-13	Modification of the main landing gear					X	X									7-Jun-1991		
1078-14	Replacement of both aileron control rods no.1					X	X									5-Jun-1990		
1078-15	Permitted modifications of the nose landing gear					X										6-May-1991		
1078-16	Replacement of fuel hose on the firewall					X	X									18-Sep-1990		
1078-17	Check of the PA bushes in the steering damper						X									19-Nov-1990		
1078-18	Replacement of bonding lead assembly VV5						X									16-May-1991		
1078-19	Permitted modifications of the nose landing gear					X	X									3-Jul-1991		
1078-20	Installation of a rudder trim plate					X	X									23-Jul-1991		
1078-21	Installation of maintenance free fuel lines					X	X									2-Dec-1991		
1078-22	Installation of an Emergency Locator Transmitter					X	X									9-Sep-1991		France only
1078-23	Installation of an additional rudder stop					X	X									16-Oct-1991		
1078-24	Inspection of the flap hinges						X									23-Jun-1992		
1078-25	Revision of the Flight Manuals G 115/ G 115A					X	X									13-Aug-1992		
1078-27/2	Modification of the G115/115A to the G115B standard					X	X									21-Apr-1993		
1078-28	Modification to the wing flap hinges						X									29-Mar-1993		
1078-29/2	Elevator lever exchange					X	X	X								12-Aug-1993		
1078-30	Inspection or modification of elevator and elevator trim.					X	X	X								13-Aug-1993		
1078-31	Installation of a GRP nose wheel fork					X	X	X								22-Sep-1993		
1078-32	Installation of equipment for VFR night, CVFR,...							X	X	X	X					3-Nov-1994		
1078-33	Modification of the nose wheel support, Installation ...							X		X	X					18-Apr-1994		
1078-34	Reduction of the never exceed speed vne										X					29-Apr-1994		
1078-35	Improvements and modifications during series							X		X	X					6-May-1994		

List of Service Bulletins



Type: **G 115**
 Plot Filter: **distributed**

Ref. TCDS No.: **EASA.A.364**
 List State: **23-May-2018**

SB No. / Issue	Title	Category				Affected Models								Issue date	Associated Change Note	Remarks		
		Alert	Mandatory	Recommended	Optional	G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E				G 115EG	G 115TA
1078-36/2	Improvements and modifications during series								X		X	X				1-Jun-1994		
1078-37	Revision of the Flight Manual G 115D2											X				3-Jun-1994		
1078-38	Stiffening of LH and RH seat shell, Installation of a..								X		X	X				16-Jun-1994		
1078-39	Revision of the Flight Man. G 115D2 (German issue)											X				20-Jun-1994		German language
1078-40	New issue Flight Manual G 115C (German issue)								X							1-May-1994		German language
1078-41	Modification to the canopy								X	X	X	X				6-Jul-1994		
1078-42	Revision of the Flight Manual G 115C								X							11-Jul-1994		
1078-43	Revision of the Flight Manuals G 115C2 G 115D2									X		X				18-Jul-1994		
1078-44	Revision of the Flight Manual G 115D										X					25-Jul-1994		
1078-45	Modifications during series production								X	X	X	X				1-Aug-1994		
1078-46	New issue Flight Manual G 115D (German issue)											X				1-Jun-1994		German language
1078-47	Revision of the Flight Manuals, new issue FM								X	X	X	X				11-Oct-1994		
1078-48	Revision of the Maintenance Manuals					X	X	X								17-Oct-1994		
1078-49	Inspection and exchange of the carburetor temp. sens.					X	X	X	X	X						5-Dec-1994		
1078-50	Revision FM, Installation of equipment for IFR								X	X	X	X				12-Dec-1994		
1078-51	Inspection and reinforcement of the main undercarriage								X	X	X	X				18-Jan-1995		
1078-52/2	Repair of the front pedal ribs, reinforced pedal levers								X	X	X	X				31-May-1996		
1078-54	Modifications and improvements to the G115C/D								X	X	X	X				1-Sep-1995		
1078-55	Use of the G115C for limited acrobatic operation								X							18-Jan-1996		
1078-56	Installation of a LIESE muffler to G115 with					X	X									12-Dec-1995		
1078-57	Replacement of the engine instruments								X	X	X	X				20-Dec-1995		
1078-58	Modifications and improvements to the G115C/D								X	X	X	X				27-Jan-1996		
1078-59/2	Reduction of the never exceed speed / acro manoeuvres								X	X	X	X				2-Sep-1996		
1078-59/3	Validation of the never exceed speed / acro manoeuvres								X	X	X	X				24-Oct-1996		
1078-60	Replacement of the airplane identification plate								X							13-Feb-1996		
1078-61	Reinforcement of the main undercarriage attachment								X	X	X	X				20-Feb-1996		
1078-62	Modification of the horizontal stabilizer attachment								X	X	X	X				5-Dec-1996		
1078-63	Optional modification of the fuel filler caps								X	X	X	X				24-Nov-1996		
1078-64/2	Exchange of the elevator hinges								X	X	X	X				8-Apr-1997		
1078-65	Modification of left and right rudder pedal unit								X	X	X	X				12-Dec-1996		
1078-66	Weights and residual moments of control surfaces								X	X	X	X				10-Feb-1997		
1078-67	Weights and residual moments of control surfaces								X	X	X	X				10-Feb-1997		
1078-68	Modification of the flap control					X	X	X								29-Apr-1997		

List of Service Bulletins



Type: **G 115**
 Plot Filter: **distributed**

Ref. TCDS No.: **EASA.A.364**
 List State: **23-May-2018**

SB No. / Issue	Title	Category				Affected Models								Issue date	Associated Change Note	Remarks		
		Alert	Mandatory	Recommended	Optional	G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E				G 115EG	G 115TA
1078-69	Cancelation of the reduction of the never exceed speed								X	X	X	X				10-Jul-1997		
1078-70	Installation of a 3-blade constant speed propeller										X					21-Oct-1997		
1078-71	Installation of a modified air filter box								X	X	X	X				27-Oct-1997		
1078-72	Installation of a modified muffler attachment bracket								X	X	X	X				4-Feb-1998		
1078-73	Securing of the lower rudder bolt					X	X	X	X	X	X	X				12-Nov-1997		
1078-74	Revision of the Flight Manual								X	X	X	X				15-Sep-1998		
1078-75	Inspection of the trim tab hinges					X	X	X	X	X	X	X				15-May-1998		
1078-76	Exchange of an oil hose								X	X	X	X				14-Sep-1998		
1078-77	Installation of a 2-piece horizontal stabilizer								X	X	X	X				5-Dec-1998		
1078-78/2	Exchange of the propeller attachment bolts											X				20-Aug-1999		
1078-83	Revision of the Flight Manual												X			13-Dec-1999		
1078-84	Various modifications												X			30-Nov-1999		
1078-85	Modification of the trim control								X	X	X	X				23-Nov-1999		
1078-86	Installation of an additional anti-icing protection										X	X				10-Nov-1999		
1078-87	Modification to the G 115D standard								X	X	X	X				17-Nov-1999		
1078-91/2	Installation of maintenance free hoses					X	X	X								7-Feb-2001		
1078-96	Horizontal Stabilizer								X		X					13-Dec-2001		
1078-98	Introduction of an UHF-Transmission Placard												X			29-Aug-2000		
1078-101	Installation of an additional anti-icing protection				X								X			10-Nov-2000		
MSB1078-103	Baggage compartment cover		X								X	X	X			3-Oct-2001	IM115-84	
OSB1078-105/1	4000 hours inspection G 115C/D				X				X	X	X	X				25-Jul-2016	MÄM 1078-196	Supersedes 1078-105
SB1078-106	Replacement of Coupling Magneto by Retarder Sys.				X								X			25-Apr-2001		
OSB1078-107	IFR operation				X								X			8-May-2002	OÄM1078-23	
MSB1078-108	Canopy jettison		X											X		27-Feb-2002	IM115-88	
MSB1078-109	Replacement of 2 Relays		X											X		12-Sep-2001	IM115EG-E30	
MSB1078-110/1	Modification fuel system		X										X	X		13-Dec-2001	MÄM1078-25	
OSB1078-111	Baggage Compartment Cover				X								X			12-Sep-2001	IM115-87	
OSB1078-112/2	Exhaust muffler installation				X				X	X	X	X	X	X		15-May-2003	IM115-90	
OSB1078-113	Alternative air filter				X								X	X		17-Sep-2001	MÄM1078-26	
MSB1078-114	Avionic Rack Installation		X											X		24-Sep-2001	MÄM1078-28	
OSB1078-115/2	Fuel tank sealant				X				X	X	X	X	X	X		21-Mar-2001	OÄM1078-29	
OSB1078-116	Instrument panel clearance				X								X			12-Nov-2001	OÄM1078-32	
OSB1078-117/3	Fuel quantity probe				X								X	X		3-May-2016	OÄM1078-29	

List of Service Bulletins



Type: **G 115**
 Plot Filter: **distributed**

Ref. TCDS No.: **EASA.A.364**
 List State: **23-May-2018**

SB No. / Issue	Title	Category				Affected Models								Issue date	Associated Change Note	Remarks	
		Alert	Mandatory	Recommended	Optional	G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E				G 115EG
OSB1078-118	Trim drive unit				X							X	X		20-Nov-2001	OÄM1078-30	
OSB1078-119	Mic/ tel lead				X							X			23-Nov-2001	OÄM1078-31	
MSB1078-120/6	Brake Master Cylinder		X									X			6-Nov-2012	OÄM1078-063	Supersedes MSB1078-120/5
MSB1078-121	Main Gear Door Actuator		X										X		25-Feb-2002		
MSB1078-122/7	Hinge Bracket		X									X			27-Mar-2009	MÄM1078-33	Supersedes 1078-122/4 & 5
OSB1078-124	Manifold pressure indication				X							X			12-Sep-2002	OÄM1078-36	
MSB1078-126/1	CO in cockpit		X			X	X	X							7-Oct-2002	MÄM1078-38	Supersedes MSB1078-126
OSB1078-127	Engine cooling air baffles				X							X			25-Jul-2002		
OSB1078-128	Landing Gear Limits				X								X		14-Jun-2002		
OSB1078-129	Hard Landing Indicator				X								X		19-Jun-2002	OÄM1078-39	
OSB1078-131	Fuel Pressure Transmitter				X							X	X		9-Aug-2002	OÄM1078-41	
MSB1078-132/1	Oil Pressure Transmitter		X									X	X		23-Sep-2002	OÄM1078-40	
OSB1078-133	Alternative Seat Harness				X	X	X	X							31-Jul-2002		
MSB1078-134	Elevator Trim		X									X			15-Oct-2002		
MSB1078-135	Exchange of the Low Fuel Sensor Circuit Breaker		X									X	X		27-Sep-2002	MÄM1078-39	
OSB1078-136	Exchange of the Air Condition Service Adaptors				X									X	19-Nov-2002	IM115-90	
MSB1078-137	Fuel line fixation		X									X	X		10-Feb-2003	MÄM1078-40	
OSB1078-140	Canopy handle cover, various canopy modifications				X							X	X		21-Mar-2003	OÄM1078-42	
OSB1078-140/1	Canopy handle cover				X							X	X		22-Sep-2005	OÄM1078-53	Supplements OSB1078-140
OSB1078-141	Modification of the engine fire extinguisher				X								X		8-Apr-2003	OÄM1078-43	
MSB1078-142/4	Aircraft documentation status G115, G115A		X			X	X								12-Oct-2016	MÄM1078-196	Supersedes MSB1078-142/3
MSB1078-143/4	Aircraft documentation status G115B		X				X								12-Oct-2016	MÄM1078-196	Supersedes MSB1078-143/3
MSB1078-144/9	Aircraft documentation status G115C, G115D		X				X	X	X	X					14-Jun-2016		Supersedes MSB1078-144/8
MSB1078-145/26	Aircraft documentation status G115E		X									X			24-Jan-2017		Supersedes MSB1078-145/25
MSB1078-146/13	Aircraft documentation status G115EG		X										X		17-May-2018		Supersedes MSB1078-146/12
MSB1078-147/8	Aircraft documentation status G115TA		X											X	31-May-2016		Supersedes MSB1078-147/7
OSB1078-148/1	Alternative ignition switch				X								X		19-Jun-2009	IM115EG-E31	
OSB1078-149	Manifold Pressure Indicator				X							X			27-May-2004		
OSB1078-150	Mixture Lean Stop Device				X							X			28-Sep-2004	OÄM1078-047	
MSB1078-151/2	Hoffmann Propeller		X				X	X	X	X	X				14-Jul-2004		Supersedes MSB1078-151/1
MSB1078-152	Inspection of Fuel Hoses / Überprüfung von		X			X	X								1-Oct-2004		
MSB1078-153	Exchange of the Main Landing Gear Swivel Bearing		X											X	22-Nov-2004	MÄM1078-48	
OSB1078-154	Mode-S Transponder				X							X			1-Dec-2006	OÄM1078-52	

List of Service Bulletins



Type: **G 115**
 Plot Filter: **distributed**

Ref. TCDS No.: **EASA.A.364**
 List State: **23-May-2018**

SB No. / Issue	Title	Category				Affected Models								Issue date	Associated Change Note	Remarks	
		Alert	Mandatory	Recommended	Optional	G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E				G 115EG
OSB1078-155	Alternative attitude gyro (Mikrotechna)				X							X			14-May-2013	OÄM1078-172	
MSB1078-156	Slick Start Booster		X									X			6-Dec-2006	MÄM1078-58	
MSB1078-157	Rudder Support Assy		X									X	X		23-Jan-2008	MÄM1078-062	
OSB1078-158	Alternate ELT				X							X			22-Sep-2008	OÄM1078-064	
OSB1078-159/1	Alternate Brake Cylinder				X	X	X	X	X	X	X	X	X	X	5-Nov-2012	OÄM1078-063	Supersedes MSB1078-159
OSB1078-160/2	Aerobatic Colour Scheme				X							X			12-Mar-2014	OÄM1078-066 MÄM1078-173	
MSB1078-161/2	Service Life Extension		X			X	X	X	X						25-Jul-2016	MÄM1078-196	Supersedes MSB1078-161/1
OSB1078-162	Securing of MLG Bolts				X			X	X	X	X	X	X		10-Jul-2009	MÄM1078-075	
MSB1078-163/2	Wing shear bolt torque		X					X	X	X	X	X	X		30-Sep-2010		Supersedes MSB1078-163/1
MSB1078-164	Canopy jettison		X					X		X		X	X		22-Jul-2009		
MSB1078-165	Nose wheel fork		X					X	X	X	X	X	X		3-Nov-2009		
MSB1078-166	Chafing protection		X									X			11-Sep-2009		
MSB1078-167	Canopy jettison		X									X			19-Nov-2009	MÄM1078-107	
MSB1078-168	Airfilterbox inspection		X			X	X	X	X	X	X	X	X		12-Nov-2009		
MSB1078-169	Inspection of the canopy lock		X					X	X	X	X	X	X		27-Nov-2009		
MSB1078-170	Inspection of the flap operating lever		X			X		X							3-Dec-2009		
MSB1078-171	Inspection of start relay		X									X			7-Dec-2009		
MSB1078-172/1	Wing shear bolt torque		X										X		22-Sep-2010		Supersedes MSB1078-172
MSB1078-173/1	Inspection and exchange of Oil Dip Stick		X									X			18-May-2010		
OSB1078-174	Marking of Canopy Jettison Handle				X			X	X	X	X	X	X		27-Jul-2010	OÄM1078-127	
RSB1078-175	Exchange of Integrated Engine Instrument			X								X			2-Jul-2010		
RSB1078-177	Canopy rear attachment			X								X	X		15-Oct-2010	MÄM1078-126	
OSB1078-178/5	Optional installation of a Traffic Advisory System				X							X			17-Feb-2011	OÄM1078-129, -133	Supersedes OSB1078-178/4
RSB1078-180/1	Improved Attachment of shimmy damper			X								X	X		19-Sep-2011	MÄM1078-135	Supersedes RSB1078-180
MSB1078-181	Instrument panel clearance		X									X			18-Apr-2011	MÄM1078-142	
RSB1078-182	Improved Canopy Lock			X						X	X	X	X		25-Nov-2011	MÄM1078-148	
OSB1078-183	Alternative Accelerometer FALCON				X							X	X		29-Jul-2011	MÄM1078-151	
OSB1078-184	Alternative Toggle switch				X	X	X	X	X	X	X	X	X		14-Feb-2012	MÄM1078-153	
MSB1078-185	Inspection of Brake Torque plate		X										X		11-Nov-2011		
MSB1078-186/4	Inspection of trim tab arm		X									X	X		13-Dec-2012	MÄM1078-161	Supersedes MSB1078-186/3
MSB1078-187/1	Inspection/Improvement of NLG		X										X		31-Aug-2012		Supersedes MSB1078-187

List of Service Bulletins



Type: **G 115**
 Plot Filter: **distributed**

Ref. TCDS No.: **EASA.A.364**
 List State: **23-May-2018**

SB No. / Issue	Title	Category				Affected Models								Issue date	Associated Change Note	Remarks	
		Alert	Mandatory	Recommended	Optional	G 115	G 115A	G 115B	G 115C	G 115C2	G 115D	G 115D2	G 115E				G 115EG
MSB1078-188	Modification of improved Canopy Locks		X									X	X		22-Jun-2012	MÄM1078-160	
MSB1078-189	Functional Test of Seat Harness		X									X	X		6-Aug-2012		
MSB1078-190	Replacement of self locking nuts		X					X	X	X	X			X	26-Nov-2012		W/N 82001-82007 with SB1078-62
MSB1078-191/1	Inspection for correct cable routing behind instrument		X									X			15-Jan-2013		Supersedes MSB1078-191
MSB1078-192	Replacement of spin recovery placard		X									X	X		23-Jan-2013	MÄM1078-169	
RSB1078-193/2	Improved Engine Oil System			X								X	X		1-Dec-2015	MÄM1078-175	Supersedes RSB1078-193/1
MSB1078-194/2	Inspection of Elevator flange		X									X	X		19-Dec-2016		Supersedes MSB1078-194/1
OSB1078-195	Removal of Owner's Name Plate				X							X			17-Mar-2014	MÄM1078-181	
MSB1078-196/1	Inspection of starter solenoid - Installation of starter relay		X									X	X		1-Dec-2014	MÄM1078-187	EASA AD 2014-0212
RSB1078-197	Modified Main Wheel Axle			X										X	30-Sep-2014	MÄM1078-189	
OSB1078-198/3	Installation of Provisions for FLARM				X							X			27-Apr-2015	OÄM1078-188	
OSB1078-199	New Aerobatic Colour Scheme				X							X			27-Apr-2015	OÄM1078-201	
MSB1078-200	Inspection of Tail Joints		X									X	X		25-Feb-2016	-	
MSB1078-201/3	Limitation of Aerobatic Operation		X				X		X	X	X	X	X	X	17-Jul-2017	-	Supersedes MSB1078-201/2
OSB1078-202/1	Additional Decals for Canopy and Fire Extinguisher				X							X			27-Apr-2018	MCN1078-230	Supersedes MSB1078-202
OSB1078-203	Alternative ELT ARTEX 1000				X								X		1-Mar-2018	OCN1078-227	