



Subject: Correction of the Flight Manual GROB G 109.

Effectivity: Motorglider GROB G 109 all serial numbers.

Accomplishment: Not later than March 31, 1983.

Reason: After considerable flight experience the take-off distances in the flight manual will be corrected. In addition further informations for powered flight operation will be made.

Instructions: To update the flight manual to revision state of 14.12.1982 the following pages have to be exchanged.

- Page 4 and 4a (supersede issue of 22.10.1981):
Revision list of 14.12.1982.
- Page 11 (supersedes issue of 1.3.81):
Colour markings of the oil temperature gage. Details to fuel.
- Page 31 (supersedes issue of 1.3.82) and
Page 36a (supersedes issue of 1.10.82):
Use of the auxiliary fuel pump.
- Page 41 (supersedes issue of 12.5.81):
Details to the take-off distances.
- Page 43 (supersedes issue of 1.3.81):
Details about range and fuel flow.

Materials: The exchange pages 4, 4a, 11, 31, 36a, 41 and 43 with date of issue 14.12.82 of the flight manual GROB G 109 have to be obtained from the manufacturer.

Mattsies, Dec. 14, 1982

i.A. Dipl. Ing. H. Wilser

Wilser

Approved by LBA



erich
28. Dez. 1982

Datum	ersetzt Ausgabe vom	Bearbeitung		Seite
-------	---------------------	-------------	--	-------