



Edition of TM 817-8 for U.S. registered gliders.

Subject: Adjustment of the Flight Manual GROB G 109.

Effectivity: Motorglider GROB G 109 all serial numbers.

Accomplishment: Not later than March 31, 1983.

Reason: After considerable flight experience the take-off distances in the flight manual will be corrected. In addition further informations for powered flight operation will be made.

Instructions: To update the flight manual to revision state of Jan.19,1983 the following pages have to be exchanged.

- Page 1 and 1a (supersede issue of June 15,1982):
Log of revisions of Jan.19,1983.
- Page 11 (supersedes issue of June 15,1982):
Colour markings of the oil temperature gage. Details to fuel.
- Page 25 and 31 (supersede issue of June 15,1982):
Use of the auxiliary fuel pump.
- Page 36 (supersedes issue of June 15,1982):
Details to the take-off distances.
- Page 39 (supersedes issue of June 15,1982):
Details about range and fuel flow.

Materials: The exchange pages 1, 1a, 11, 25, 31, 36 and 39 with date of issue Jan.19,1983 of the flight manual GROB G 109 have to be obtained from the manufacturer.

Mattsies, Jan.19, 1983

Approved by LBA

i. A. Dipl. Ing. H. Wilser



Peris
2. Feb. 1983

Datum	ersetzt Ausgabe vom	Bearbeitung		Seite
-------	---------------------	-------------	--	-------