

I 374 F 21/1



Service Bulletin
TM 1078-6

GROB
G 115

Subject: Approval of installation of a primer system

Effectivity: GROB G 115
s/n 8007 and on

Accomplishment: Optional


Reason: For better engine starting in cold weather it is recommended to install a primer system.

The system will be installed at customer request.

Instructions: The modification has to be installed according to drawing no. 115-6290 and installation instruction no. 1078-6.

Weight and Balance: No effect

Remarks: The correct installation has to be certified in the log-book by an authorized inspector.



Mattsies, 20 December 1988

LBA-approved:

Rolof hsk

20. Feb. 1989

signed R. Rischer

Flak

P.S.: The translation has been done to the best knowledge and judgement. In any case or doubt, the German original is authoritative.

Datum 20 Dec 88	ersetzt Ausgabe vom	Bearbeitung J. Altmann	Musterprüfer	Seite 1 of 1
--------------------	---------------------	---------------------------	--------------	-----------------